

Wheels and Tires: Recalls

Recall 07V038000: Front Hub/Bearing Replacement

MAKE/MODELS: MODEL/BUILD YEARS:

Dodge/RAM 2006

MANUFACTURER: DaimlerChrysler Corporation

NHTSA CAMPAIGN ID NUMBER: 07V038000 MFG'S REPORT DATE: February 06, 2007

COMPONENT: Suspension: Front: Wheel Bearing

POTENTIAL NUMBER OF UNITS AFFECTED: 86333

SUMMARY:

On certain pickup trucks, the front wheel bearing may have received an insufficient quantity of grease during the manufacturing process.

CONSEQUENCE:

This could result in bearing degradation, and if subsequent noise and vibration are ignored, could result in hub assembly separation. This may result in a loss of vehicle control and cause a crash without warning.

REMEDY:

Dealers will replace the front hub and bearing units. The recall is expected to begin during February 2007. Owners may contact DaimlerChrysler at 1-800-853-1403.

NOTES:

DaimlerChrysler recall No. G02. Customers may also contact The National Highway Traffic Safety Administration's Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to <http://www.safercar.gov>.