


REPLACEMENT


1. Disconnect the negative (-) battery terminal.
2. Remove the crash pad garnish (A) after pulling it by using regular screw driver (-). Take care of fixing clips (C).
3. Remove the center facia panel (B) after loosening the screws.



ETRF021B

Fig. 10: Identifying Crash Pad Garnish, Center Facia Panel And Clips
Courtesy of HYUNDAI MOTOR CO.


4. Remove the connectors (A).



LSRE170G

Fig. 11: Identifying Connectors
Courtesy of HYUNDAI MOTOR CO.

5. Remove the mounting screws then remove the audio unit (A).



ETRF021C

[Fig. 12: Identifying Audio Unit Mounting Screws](#)
Courtesy of HYUNDAI MOTOR CO.

6. Installation is the reverse of removal.