

2001 Hyundai Sonata

2001 ACCESSORIES/SAFETY EQUIPMENT Hyundai - Air Bag Restraint Systems

DIAGNOSTIC TROUBLE CODE (DTC) IDENTIFICATION

DTC	Scan Tool Display
B1111	Battery voltage high
B1112	Battery voltage low
B1346	Driver-side air bag resistance high
B1347	Driver-side air bag resistance low
B1348	Driver-side air bag short to ground
B1349	Driver-side air bag short to battery
B1352	Passenger-side air bag resistance high
B1353	Passenger-side air bag resistance low
B1354	Passenger-side air bag short to ground
B1355	Passenger-side air bag short to battery
B1361	Driver-side seat belt pretensioner resistance high
B1362	Driver-side seat belt pretensioner resistance low
B1363	Driver-side seat belt pretensioner short to ground
B1364	Driver-side seat belt pretensioner short to battery
B1367	Passenger-side seat belt pretensioner resistance high
B1368	Passenger-side seat belt pretensioner resistance low
B1369	Passenger-side seat belt pretensioner short to ground
B1370	Passenger-side seat belt pretensioner short to battery
B1378	Driver side impact air bag resistance high
B1379	Driver side impact air bag resistance low
B1380	Driver side impact air bag short to ground
B1381	Driver side impact air bag short to battery
B1382	Passenger side impact air bag resistance high
B1383	Passenger side impact air bag resistance low
B1384	Passenger side impact air bag short to ground
B1385	Passenger side impact air bag short to battery
B1400	Satellite left side defective
B1401	Satellite left side short to ground
B1402	Satellite left side short to battery
B1403	Satellite right side defective
B1404	Satellite right side short to ground
B1405	Satellite right side short to battery
B1406	PPD defective
B1407	PPD communication error
B1408	Satellite left communication error
B1409	Satellite right communication error
B1620	Internal fault
B1650	SRSCM crash recorded (replace SCRSM)
B1651	Crash recorded driver-side air bag

2001 Hyundai Sonata

2001 ACCESSORIES/SAFETY EQUIPMENT Hyundai - Air Bag Restraint Systems

<u>B1652</u>	Crash recorded passenger-side air bag
<u>B1661</u>	SRSCM mismatching (replace SCRSM)
<u>B2500</u>	AIR BAG warning light failure